


Hummer H2

1. First, remove trim panel by removing screws that hold cluster trim panel to instrument panel
2. Use care to remove cluster trim panel from tabs in instrument panel



3. Now, remove the screws from the instrument cluster



4. Finally, disconnect the instrument cluster electrical connection.

